

www.nuvitechemical.com 800.394.8351 • 516.935.4000





Rid

SURFACE CLEANER & REODORIZER


Industrial Strength Cleaner for Galley & Lavatory



LAVATORY CLEANING

- 1. Dilute **Rid** 1:4 to 1:8* with water.
- 2. Spray on terry towel or directly on surface to thoroughly coat area.
- 3. For grained plastics, use a soft brush.
- 4. Wipe with terry towel & leave to air dry.





- 2. Spray directly onto surface, thoroughly coat area.
- 3. Allow to soak 2-3 minutes.
- 4. Wipe dry with terry towel.



FOR FLOORS

- 1. Dilute **Rid** 1:8 to 1:12* with water.
- 2. Use mop head to apply to surface
- 3. Allow to soak 2-3 minutes.
- 4. Dry with clean, dry mophead.

*Product dilutions are determined by extent, condition & soil type.

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.

QUESTIONS? NUVITE technicians have the answers 800.394.8351