

www.nuvitechemical.com 800.394.8351 • 516.935.4000





Nulmage

CLEANER & DEBUGGER FOR POLISHED METAL

For cleaning stubborn bug residue, perfect for touch-ups in between polishing



GENERAL CLEANING

- 1. Pour a small amount of **Nulmage** onto a flannel polishing cloth.
- 2. Apply to surface, wiping on gently to avoid scratching from surface soils & dust.
- Gently spread material over target polish area.
- Rub until **Nulmage** is removed.
- 5. Slight haze will remain, allow to dry.
- 6. After haze has dried completely, polish away to bright shine with clean cotton flannel polishing cloth.



STUBBORN BUG REMOVAL

- 1. Wet bug spot with **Nulmage**.
- 2. Spread material on area around bug while **Nulmage** soaks bug material.
- 3. After a few seconds, rub away bug residue.
- 4. Keep any remaining bug residue wet & soaking.
- 5. Remove with gentle rubbing.
- 6. Repeat until bug spot is disappeared.

*Product dilutions are determined by extent, condition & soil type.

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.

QUESTIONS? NUVITE technicians have the answers 800.394.8351